



# CONSTRUCTION EQUIPMENT

## VOLVO L90G 4112 - FRONT AXLE



**Sample No:** VC05996068  
**Oil Type:** VOLVO WB 102  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VC05996068	---	---	---
Sample Date	20 Oct 2023	---	---	---
Machine Hours	14803	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**PICK N PULL**  
 PO BOX 10636  
 PORTLAND, OR  
 US 97296  
 Contact:



### OIL CONDITION

Visc @ 40°C	cSt	█ 44.9	---	---	---
-------------	-----	--------	-----	-----	-----

T:  
F:



### CONTAMINATION

Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ 0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 7	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 3159	---	---	---
Magnesium	ppm	█ 54	---	---	---
Zinc	ppm	█ 1328	---	---	---
Phosphorus	ppm	█ 1121	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 108	---	---	---

**Depot:** PICPOROR  
**Unique No:** 10724428  
**Signed:** Wes Davis  
**Report Date:** 02 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

