

CONSTRUCTION EQUIPMENT 400846 VOLVO ECR235E 315496 - DIESEL ENGINE



Sample No: VCP431472

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 400846

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

1703

445

1081

894

5

26

VOLVO				
SAMPLE	NFORMATION			
Sample Number		VCP431472	VCP418906	
Sample Date		27 Oct 2023	24 May 2023	
Machine Hours		1024	466	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO	ITION			
OIL COND	IIIUN	<u>.</u>		
Visc @ 100°C	cSt	12.6	13.1	
Base Number (BN)		10.0	□7.2	
Oxidation (PA)	%	80	43	
CONTAM	NATION			
Soot %	%	0.1	□0.1	
Nitration (PA)	%	60	55	
Sulfation (PA)	%	60	50	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	<1.0	
Silicon	ppm	110	18	
Sodium	ppm	■0	2	
Potassium	ppm	1	4	
			_	
VOLVO	TALE			
WEAR MI	ETALS			
ron	ppm	13	2 2	
Copper	ppm	■ 3	1 3	
_ead	ppm	0	1	
Γin	ppm	■ <1	2	
Aluminum	ppm	1	6	
Chromium	ppm	■ <1	2	
Molybdenum	ppm	44	■50	
Vickel	ppm	■ 2	1 0	
Titanium	ppm	0	<1	
Silver	ppm	■ <1	0	
Manganese	ppm	■ <1	5	
Vanadium	ppm	0	0	

2862

1244

1058

0

99



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO0096Unique No:10724924Signed:Wes DavisReport Date:03 Nov 2023



CONSTRUCTION EQUIPMENT





