



CONSTRUCTION EQUIPMENT

SPM554027 KAMPS VOLVO L70H 623552 - REAR AXLE



Sample No: VCP382991
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No: SPM554027 KAMPS



ALTA EQUIPMENT COMPANY- BYRON CENTER
 8840 BYRON COMMERCE DR SW
 BYRON CENTER, MI
 US 49315
 Contact: BRIAN RESER
 brian.reser@altaequipment.com
 T: (616)878-7450
 F: (616)878-7650



SAMPLE INFORMATION

Sample Number	VCP382991	---	---	---
Sample Date	25 May 2023	---	---	---
Machine Hours	4065	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 42.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 54	---	---	---
Copper	ppm	█ 21	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3255	---	---	---
Magnesium	ppm	█ 24	---	---	---
Zinc	ppm	█ 1233	---	---	---
Phosphorus	ppm	█ 966	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 134	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0046
Unique No: 10725883
Signed: Wes Davis
Report Date: 03 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

