



CONSTRUCTION EQUIPMENT

GROOT VOLVO L150H 6799 - COOLANT



Sample No: VCP433146
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: GROOT



SAMPLE INFORMATION

Sample Number	VCP433146	---	---	---
Sample Date	04 Nov 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT

2500 WESTWARD DR
 SPRING GROVE, IL
 US 60081

Contact: JOHN DODGE
 john.dodge@altg.com

T:
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.95	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 748	---	---	---
Percentage Glycol	%	■ 51.0	---	---	---
Freezing Point	°C	■ -38	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Green	---	---	---

Depot: ALTSPR
Unique No: 10726692
Signed: Jonathan Hester
Report Date: 07 Nov 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

