



CONSTRUCTION EQUIPMENT

VOLVO EC200EL EC200EL3 14507 - COOLANT



Sample No: VCP0008098

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP0008098	---	---	---
Sample Date	01 Nov 2023	---	---	---
Machine Hours	1643	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com

T:
F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	8.03	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	---	---	---
Percentage Glycol	%	47.1	---	---	---
Freezing Point	°C	-28	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0092
Unique No: 10726693
Signed: Jonathan Hester
Report Date: 07 Nov 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

