



# CONSTRUCTION EQUIPMENT

## VOLVO L110H VOLVO L110H (S/N NOT GIVEN) - REAR AXLE



**Sample No:** VCP413419  
**Oil Type:** TDH FLUID SAE 75W80  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP413419	---	---	---
Sample Date	05 Nov 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**AARON GIBSON**  
 100 HUFFMAN RD  
 BROKEN BOW, OK  
 US 74728  
 Contact: AARON GIBSON  
 aarongibson@hotmail.com  
 T: (580)306-0203  
 F:



### OIL CONDITION

Visc @ 40°C	cSt	█ 47.9	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 10	---	---	---
Potassium	ppm	█ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 113	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 3167	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1345	---	---	---
Phosphorus	ppm	█ 1116	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 112	---	---	---

**Depot:** AARBRO  
**Unique No:** 10727739  
**Signed:** Doug Bogart  
**Report Date:** 07 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

