



CONSTRUCTION EQUIPMENT

VOLVO A40G 353384 - BOGIE/CENTER AXLE



Sample No: VCP432154
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No:



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP432154	---	---	---
Sample Date	02 Nov 2023	---	---	---
Machine Hours	1237	---	---	---
Oil Hours	1237	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	▲ 51.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 3	---	---	---
Sodium	ppm	■ 3	---	---	---
Potassium	ppm	■ 4	---	---	---



WEAR METALS

Iron	ppm	■ 338	---	---	---
Copper	ppm	■ 3	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 4	---	---	---
Molybdenum	ppm	■ 4	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 11	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	▲ 15	---	---	---
Magnesium	ppm	■ 0	---	---	---
Zinc	ppm	▲ 15	---	---	---
Phosphorus	ppm	▲ 2228	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 206	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0093
Unique No: 10727756
Signed: Don Baldrige
Report Date: 08 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

