

CONSTRUCTION EQUIPMENT
SPM621247 SEG 30 CATERPILLAR 349 2000820 - DIESEL ENGIN

Sample No: VCP431280

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: SPM621247 SEG 30

| TIONER | | | |
|--------------------|-------------|------|--|
| SAMPLE INFORMATION | | | |
| Sample Number | VCP431280 | | |
| Sample Date | 26 Oct 2023 | | |
| Machine Hours | 8116 | | |
| Oil Hours | 0 | | |
| Oil Changed | Changed | | |
| Sample Status | NORMAL | | |
| | | | |

| OIL CONDITION | | | | | |
|------------------|----------|-------------|--|--|--|
| Visc @ 100°C | cSt | 12.8 | | | |
| Base Number (BN) | mg KOH/g | ■8.0 | | | |
| Oxidation (PA) | % | 70 | | | |

| CONTAN | MINATION | | | |
|----------------|----------|------------|------|--|
| Soot % | % | ■ 0.4 | | |
| Nitration (PA) | % | 83 | | |
| Sulfation (PA) | % | 59 | | |
| Glycol | % | NEG | | |
| Fuel | % | <1.0 | | |
| Silicon | ppm | ■ 5 | | |
| Sodium | ppm | 0 | | |
| Potassium | ppm | 2 | | |

| WEAR I | METALS | | | |
|------------|--------|---------------|------|--|
| Iron | ppm | 19 | | |
| Copper | ppm | ■ 3 | | |
| Lead | ppm | 1 | | |
| Tin | ppm | -<1 | | |
| Aluminum | ppm | 2 | | |
| Chromium | ppm | -<1 | | |
| Molybdenum | ppm | 44 | | |
| Nickel | ppm | ■<1 | | |
| Titanium | ppm | 23 | | |
| Silver | ppm | ■ 0 | | |
| Manganese | ppm | -<1 | | |
| Vanadium | ppm | <1 | | |
| | | | | |

| ADDIT | IVES | | | |
|------------|------|-------------|------|--|
| Calcium | ppm | 1277 | | |
| Magnesium | ppm | ■745 | | |
| Zinc | ppm | 1188 | | |
| Phosphorus | ppm | ■1051 | | |
| Barium | ppm | ■5 | | |
| Boron | ppm | 1 3 | | |



ADAMO DEMOLITION COMPANY

320 EAST 7 MILE RD DETROIT, MI US 48203

Contact: SERVICE MANAGER

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: **ADADET Unique No:** 10728566 Signed: Sean Felton Report Date: 08 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPH

