CONSTRUCTION EQUIPMENT 607995 DIPRO POLARIS RANGOR 34243 - FRONT AXLE

Sample No:VCP431913Oil Type:POLARIS FRONT AXLE OILJob No:607995 DIPRO

VOLVO

Silver

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

SAMPLE INFORMATION						
Sample Number		VCP431913				
Sample Date		10 Oct 2023				
Machine Hours		995				
Oil Hours		995				
Oil Changed		Changed				
Sample Status		NORMAL				
Visc @ 40°C	cSt	39.1				
VOLVO						
CONTAMINATION						
Silicon	ppm	9				
Sodium	ppm	6				
Potassium	ppm	0				
VOLVO						
WEAR METALS						
Iron	ppm	54				
Copper	ppm	6				
Lead	ppm	0				
Tin	ppm	0				
Aluminum	ppm	4				
Chromium	ppm					
Molybdenum	ppm	2				
Nickel	ppm	0				
Titanium	ppm	0				



ALTA EQUIPMENT COMPANY - METRO WEST

56195 PONTIAC TRAIL NEW HUDSON, MI US 48165 Contact: PAUL CONZ paul.conz@altg.com T: (313)348-8861 F: (248)356-2029

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO2990		
Unique No:	10735605		
Signed:	Sean Felton		
Report Date:	10 Nov 2023		

0

2

0

2669

1242

913

0

10

24

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm


ADDITIVES

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO2990 [WUSCAR] 06001843 (Generated: 11/12/2023 16:24:29) Rev: 1

Contact/Location: PAUL CONZ - VOLVO2990