



CONSTRUCTION EQUIPMENT

VOLVO A25 752474 - REAR AXLE



Sample No: VCP432805
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No:



SAMPLE INFORMATION

Sample Number	VCP432805	---	---	---
Sample Date	07 Nov 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: BRAD BYRO
 bradley.byro@altg.com
 T: (407)850-9614
 F: (407)659-8720

OIL CONDITION

Visc @ 40°C	cSt	▲ 89.0	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Silicon	ppm	■ 5	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 2	---	---	---

WEAR METALS

Iron	ppm	■ 186	---	---	---
Copper	ppm	■ 19	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 4	---	---	---
Molybdenum	ppm	■ 3	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 8	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 717	---	---	---
Magnesium	ppm	■ 3	---	---	---
Zinc	ppm	■ 315	---	---	---
Phosphorus	ppm	▲ 1314	---	---	---
Barium	ppm	■ 5	---	---	---
Boron	ppm	▲ 260	---	---	---

Diagnosis
 The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0096
Unique No: 10735633
Signed: Sean Felton
Report Date: 10 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

