



CONSTRUCTION EQUIPMENT

DIPRO VOLVO A40G 353052 - COOLANT



Sample No: VCP431921
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: DIPRO



SAMPLE INFORMATION

Sample Number	VCP431921	---	---	---
Sample Date	25 Oct 2023	---	---	---
Machine Hours	6429	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY - METRO WEST
 56195 PONTIAC TRAIL
 NEW HUDSON, MI
 US 48165
 Contact: PAUL CONZ
 paul.conz@altg.com
 T: (313)348-8861
 F: (248)356-2029



COOLANT CONDITION

pH	Scale 0-14	■ 7.26	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 44.5	---	---	---
Freezing Point	°C	■ -21	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO2990
Unique No: 10735803
Signed: Doug Bogart
Report Date: 16 Nov 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

