

# CONSTRUCTION EQUIPMENT 368 JOHN DEERE 814867 - SWING DRIVE



Sample No: VCP413618

Oil Type: SHELL TELLUS 80W90

**Job No:** 368

SAMPLE	INFORMATIO	N		
Sample Number		VCP413618	 	
Sample Date		19 Oct 2023	 	
Machine Hours		4805	 	
Oil Hours		1000	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
		-		
OIL CON	DITION			
Visc @ 40°C	cSt	<b>187</b>	 	
VI3C @ 40 C	CSt	<b>107</b>		
VOLVO				
CONTAN	MOITAMIN			
Silicon	ppm	<b>17</b>	 	
Sodium	ppm	<b>■&lt;1</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR N	METALS			
Iron	ppm	<b>61</b>	 	
Copper	ppm	<b>■</b> 0	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	24	 	
Magnesium	ppm	4	 	
Zinc	ppm	12	 	
Phosphorus	ppm	502	 	
Barium	ppm	2	 	
Boron	ppm	72	 	

#### TOTAL DEVELOPMENT SOLUTIONS LLC

7805 PROGRESS CT
GAINESVILLE, VA
US 20155
Contact: JOE SEALE
jseale@totaldevelopmentsolutions.com
T: (703)222-0497
F: (703)753-4586

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:TOTGAIUnique No:10736300Signed:Wes DavisReport Date:09 Nov 2023

Contact/Location: JOE SEALE - TOTGAI



## **CONSTRUCTION EQUIPMENT**





