

CONSTRUCTION EQUIPMENT VOLVO EC220E 314249 - SWING DRIVE



Sample No: VCP388532
Oil Type: VOLVO 90W

Job No:

SAMPLE INFORMATION Sample Number VCP388532 Sample Date 07 Nov 2023 Machine Hours 1121 Oil Hours 0 Oil Changed Changed Sample Status MARGINAL Visc @ 40°C cSt 168	- - -
Sample Number VCP388532	-
Sample Date 07 Nov 2023 Machine Hours 1121 Oil Hours 0 Oil Changed Changed Sample Status MARGINAL Visc @ 40°C cSt 168	-
Machine Hours 1121 Oil Hours 0 Oil Changed Sample Status MARGINAL Oll CONDITION Visc @ 40°C cSt 168	-
Oil Hours 0 Oil Changed Changed Sample Status MARGINAL OIL CONDITION Visc @ 40°C cSt 168	-
Sample Status MARGINAL OIL CONDITION Visc @ 40°C	-
Sample Status MARGINAL OIL CONDITION Visc @ 40°C	
OIL CONDITION Visc @ 40°C	
OIL CONDITION Visc @ 40°C	
Visc @ 40°C	
THOU THOU	
CONTAMINATION	
Water % 0.112	
Potassium ppm	
VOLVO	
WEAR METALS	
Iron ppm ■689	
Copper ppm 14	
Lead ppm 0	
Tin ppm 0	
Aluminum ppm □<1	
Chromium	
Molybdenum ppm 0	
Nickel ppm	
Titanium ppm <1	
Silver ppm 0	
Manganese ppm 9	
Vanadium ppm 0	
ADDITIVES	
Calcium ppm 7	
Magnesium ppm 4	
Zinc ppm 51	
Phosphorus ppm 438	
Barium ppm 3	
Boron	



RECYCLE 1
4700 LAWRENCE ST
HYATTSVILLE, MD
US 20781
Contact: MIKE DESJARDINS
mdesjarkins@wbwaste.com
T:
F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of visible silt present in the sample. The condition of the oil is acceptable for the time in service.

Depot:RECHYAUnique No:10736948Signed:Doug BogartReport Date:22 Nov 2023



CONSTRUCTION EQUIPMENT





