



CONSTRUCTION EQUIPMENT

VOLVO A40G 352349 - FRONT AXLE



Sample No: VCP395128
Oil Type: MOBIL MOBILUBE HD PLUS 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP395128	VCP406460	VCP404896	VCP390567
Sample Date	30 Oct 2023	29 Aug 2023	22 Mar 2023	13 Feb 2023
Machine Hours	6234	5785	4695	4463
Oil Hours	449	1090	968	736
Oil Changed	Not Chngd	Changed	Changed	Not Chngd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	130	131	132	132
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	6	3	1	3
Sodium	ppm	<1	0	<1	<1
Potassium	ppm	0	<1	0	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	81	19	30	68
Copper	ppm	1	0	<1	0
Lead	ppm	0	0	0	0
Tin	ppm	0	0	0	0
Aluminum	ppm	<1	0	0	<1
Chromium	ppm	<1	<1	<1	<1
Molybdenum	ppm	<1	0	<1	<1
Nickel	ppm	0	0	0	0
Titanium	ppm	0	0	0	<1
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	1	2
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	434	411	301	327
Magnesium	ppm	0	8	6	10
Zinc	ppm	158	138	118	112
Phosphorus	ppm	991	1019	973	899
Barium	ppm	0	0	0	0
Boron	ppm	166	198	172	171

Depot: SCHGRE
Unique No: 10736967
Signed: Wes Davis
Report Date: 10 Nov 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

