

## **CONSTRUCTION EQUIPMENT**

SPM621611 SENNEBOGEN 835 835.0.2465 - LEFT SWING DRIVE

Sample No: VCP440560

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SPM621611

VOLVO					
SAMPLE INFORMATION					
Sample Number	-	VCP440560			
Sample Date		18 Oct 2023			
Machine Hours		8621			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>215</b>			
VISC @ 40 C	CSt				
VOLVO					
CONTAM	INATION				
Water	%	<b>△</b> 0.325			
Silicon	ppm	<b>2</b>			
Sodium	ppm	<b>0</b>			
Potassium	ppm	■2			
VOLVO					
WEAR METALS					
Iron	ppm	<b>418</b>			
Copper	ppm	<b>■</b> 9			
Lead	ppm	<b>■</b> 0			
Tin	ppm	<b>1</b>			
Aluminum	ppm	<b>■</b> <1			
Chromium	ppm	<b>■</b> 4			
Molybdenum	ppm	<b>■</b> <1			
Nickel	ppm	■0			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	<b>■</b> 2			
Vanadium	ppm	0			
VOLVO					
ADDITIVI	23				
Calcium	ppm	<b>0</b>			
Magnesium	ppm	■0			
Zinc	ppm	<b>0</b>			
Phosphorus	ppm	■323			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>13</b>			



ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8885Unique No:10738394Signed:Don BaldridgeReport Date:14 Nov 2023



## **CONSTRUCTION EQUIPMENT**





