

Sample No: VCP430939

Oil Type: MOBIL MOBILUBE HD 80W90

**Job No:** A11436 JMC

SAMPLE	INFORMATION				
Sample Number		VCP430939	VCP296039		
Sample Date		03 Nov 2023	18 Dec 2020		
Machine Hours		1410	465		
Oil Hours		600	465		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
OIL CONDITION					
Visc @ 40°C	cSt	292	91.7		
Visc @ 40 C	CSt	232	91.1		
VOLVO					
CONTAM	IINATION				
Silicon	ppm	<b>11</b>	<b>9</b>		
Sodium	ppm	<b>■&lt;1</b>	<b>2</b>		
Potassium	ppm	<b>0</b>	<b>0</b>		
WEAR M	IETALS				
Iron	ppm	<b>224</b>	<b>160</b>		
Copper	ppm	<b></b>	<b>3</b>		
Lead	ppm	<b>0</b>	<b>0</b>		
Tin	ppm	<b>■</b> 0	0		
Aluminum	ppm	■0	<b>1</b>		
Chromium	ppm	<b>4</b>	<b>6</b>		
Molybdenum	ppm	■0	<b>1</b> 6		
Nickel	ppm	<b>■</b> 0	<1		
Titanium	ppm	0	1		
Silver	ppm	0	0		
Manganese	ppm	<b>2</b>	<b>4</b>		
Vanadium	ppm	0	0		
VOLVO					
ADDITIV	ES				
Calcium	ppm	■371	■3807		
Magnesium	ppm	<b>4</b>	<b>1</b> 0		
Zinc	ppm	<b>147</b>	<b>692</b>		
Phosphorus	ppm	■956	<b>565</b>		
Barium	ppm	<b>5</b>	■34		
Boron	ppm	<b>143</b>	<b>1</b> 6		



## **HOFFMAN EQUIPMENT - LIONVILLE**

120 GORDON DRIVE LIONVILLE, PA US 19341 Contact: JIM FEHR jim.fehr@hoffmanequip.com T: (610)363-9200 F: (610)594-0829

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8879Unique No:10738403Signed:Don BaldridgeReport Date:14 Nov 2023



## **CONSTRUCTION EQUIPMENT**





## **GRAPHS**

