



CONSTRUCTION EQUIPMENT

SPM621417 SENNEBOGEN 825ME 825.0.3425 - FRONT AXLE



Sample No: VCP415038
Oil Type: GEAR OIL SAE 80W90
Job No: SPM621417



SAMPLE INFORMATION

Sample Number	VCP415038	VCP423411	VCP405737	VCP363619
Sample Date	18 Oct 2023	08 Jun 2023	29 Mar 2023	06 Sep 2022
Machine Hours	7157	5757	5489	3985
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Not Changd	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

ALL AMERICAN RECYCLING
11900 S COTTAGE GROVE AVE
CHICAGO, IL
US 60628
Contact: TOM BOCHENEK
ferrous@aarecyclcles.com
T: (815)735-9892
F:



OIL CONDITION

Visc @ 40°C	cSt	142	186	186	187
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	6	22	24	23
Sodium	ppm	<1	1	2	<1
Potassium	ppm	0	<1	0	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	56	26	18	11
Copper	ppm	1	9	4	3
Lead	ppm	0	<1	0	0
Tin	ppm	0	<1	0	0
Aluminum	ppm	0	<1	1	1
Chromium	ppm	0	<1	<1	<1
Molybdenum	ppm	0	<1	<1	<1
Nickel	ppm	0	<1	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	<1	0	0
Manganese	ppm	1	2	2	2
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	325	2440	2396	2394
Magnesium	ppm	2	14	16	13
Zinc	ppm	158	1113	996	990
Phosphorus	ppm	504	858	822	837
Barium	ppm	0	0	0	0
Boron	ppm	0	10	10	0

Depot: ALLCHIL
Unique No: 10738442
Signed: Sean Felton
Report Date: 14 Nov 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

