

CONSTRUCTION EQUIPMENT

633380 ALTA RENTS VOLVO EC380 315583 - HYDRAULIC SYSTE

Sample No: VCP434607

Silver

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm


ppm

ppm

ADDITIVES

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No: 633380 ALTA RENTS





ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0093Unique No:10739257Signed:Wes DavisReport Date:14 Nov 2023

0

0

66

■0

546

393

0

0

0



CONSTRUCTION EQUIPMENT





GRAPHS

