

# CONSTRUCTION EQUIPMENT VOLVO A40G 340663 - TRANSMISSION



Sample No: VCP436178

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No:

CVMDIE	INFORMATIO	<b>1</b>		
	. INFURMATIU	<u> </u>		
Sample Number		VCP436178	 	
Sample Date		31 Oct 2023	 	
Machine Hours		10474	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	27.7	 	
VISC @ 40 C	CSI	21.1	 	
VOLVO				
<b>CONTAM</b>	INATION			
Silicon	ppm	<b>4</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<1	 	
	1-1-	_		
VOLVO	IFT ALC			
WEAR M	JE I ALS			
Iron	ppm	<b>9</b>	 	
Copper	ppm	<b>■</b> 3	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>-&lt;1</b>	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	<b>■</b> 0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	IFS			
Calcium	ppm	□74	 	
Magnesium	ppm	<b>0</b>	 	
Zinc		<b>■</b> 1	 	
Phosphorus	ppm	<b>191</b>	 	
Barium	ppm	<b>■</b> 0	 	
Boron	ppm	<b>■</b> 85	 	
וטוטוו	ppm	<b>0</b> 00		



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10739783Signed:Jonathan HesterReport Date:15 Nov 2023



## **CONSTRUCTION EQUIPMENT**





