



# CONSTRUCTION EQUIPMENT

## 9943 VOLVO A30G 753149 - FRONT AXLE



**Sample No:** VCP413676  
**Oil Type:** VOLVO PREMIUM GEAR OIL 80W-90 GL-5  
**Job No:** 9943



### SAMPLE INFORMATION

Sample Number	VCP413676	---	---	---
Sample Date	06 Nov 2023	---	---	---
Machine Hours	530	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

**MCCLUNG-LOGAN EQUIPMENT CO - CHESAPEAKE**  
 4112 HOLLAND BLVD  
 CHESAPEAKE, VA  
 US 23323  
 Contact: TOMMY GRIFFIN  
 tgriffin@mcclung-logan.com  
 T: (757)485-3314  
 F: (757)485-3415

### OIL CONDITION

Visc @ 40°C	cSt	▲ 101	---	---	---
-------------	-----	-------	-----	-----	-----

### CONTAMINATION

Silicon	ppm	■ 3	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 4	---	---	---

### WEAR METALS

Iron	ppm	■ 282	---	---	---
Copper	ppm	■ 16	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 5	---	---	---
Molybdenum	ppm	■ 3	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 10	---	---	---
Vanadium	ppm	0	---	---	---

### ADDITIVES

Calcium	ppm	■ 251	---	---	---
Magnesium	ppm	■ <1	---	---	---
Zinc	ppm	■ 118	---	---	---
Phosphorus	ppm	■ 1325	---	---	---
Barium	ppm	■ <1	---	---	---
Boron	ppm	■ 265	---	---	---

**Diagnosis**  
 The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

**Depot:** VOLVO0264  
**Unique No:** 10740961  
**Signed:** Don Baldrige  
**Report Date:** 16 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

