



CONSTRUCTION EQUIPMENT

SWA410045-10 VOLVO L120E 632377 - COOLANT



Sample No: VCP432717
Oil Type: EXTENDED LIFE COOLANT
Job No: SWA410045-10



SAMPLE INFORMATION

Sample Number	VCP432717	VCP368000	VCP341464	---
Sample Date	08 Nov 2023	24 Jan 2023	14 Apr 2022	---
Machine Hours	10919	9215	0	---
Sample Status	NORMAL	NORMAL	NORMAL	---



COOLANT CONDITION

pH	Scale 0-14	7.78	7.37	7.09	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	NT	---
Percentage Glycol	%	56.1	56.7	56.5	---
Freezing Point	°C	-50	-50	-50	---



CONTAMINATION

Coolant Appearance	normal	normal	normal	---
Coolant Color	Red	Red	Orange	---



ALTA EQUIPMENT COMPANY
 1035 WYLIE DRIVE
 BLOOMINGTON, IL
 US 61705
 Contact: MIKE MARTIN
 mike.martin@altaequipment.com
 T:
 F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO5054
Unique No: 10741738
Signed: Doug Bogart
Report Date: 29 Nov 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

