


CONSTRUCTION EQUIPMENT

SWA413501 SENNOBOGEN 835 835.0.2289 - RIGHT SWING DRIV

Sample No: VCP414800

Oil Type: GEAR OIL SAE 80W90

Job No: SWA413501





ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. The iron level is abnormal. There is a high concentration of water present in the oil. Excessive free water present. The oil viscosity is higher than normal. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO8885Unique No:10742966Signed:Angela BorellaReport Date:17 Nov 2023



CONSTRUCTION EQUIPMENT





