

## **CONSTRUCTION EQUIPMENT**

SWA413501 SENNOBOGEN 835 835.0.2289 - FRONT LEFT FINAL

Sample No: VCP414799

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SWA413501

NFORMATION				
-	VCP414799			
	13 Nov 2023			
	7801			
	0			
	Not Changd			
	NORMAL			
OIL CONDITION				
cSt	<b>160</b>			
NATION				
	<b>6</b>			
	_			
ppiii	_ ``			
TALS				
ppm	<b>■</b> 56			
ppm	<b>■</b> 5			
ppm	<b>0</b>			
ppm	<b>■</b> 0			
ppm	<b>■&lt;1</b>			
ppm	<b>■&lt;1</b>			
ppm	<b>■&lt;1</b>			
ppm	<b>0</b>			
ppm	0			
ppm	0			
ppm	<b>■&lt;1</b>			
ppm	0			
2				
ppm	■881			
ppm	<b>6</b>			
ppm	<b>234</b>			
ppm	■2599			
ppm	<b>7</b>			
	ppm	VCP414799  13 Nov 2023  7801  0 Not Changd NORMAL  TION  cSt	VCP414799  13 Nov 2023  7801  0  Not Changd  NORMAL  TION  cSt	VCP414799  13 Nov 2023  7801  Not Changd  NORMAL  TION  CSt



ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8885Unique No:10742971Signed:Angela BorellaReport Date:17 Nov 2023



## **CONSTRUCTION EQUIPMENT**





## **GRAPHS**

