



CONSTRUCTION EQUIPMENT

W02007731 VOLVO A40E 13778 - REAR AXLE



Sample No: VCP338928
Oil Type: MOBIL MOBILUBE HD 85W140
Job No: W02007731



SAMPLE INFORMATION

Sample Number	VCP338928	---	---	---
Sample Date	10 Nov 2023	---	---	---
Machine Hours	10142	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

MCCLUNG-LOGAN EQUIPMENT CO - MANASSAS
8450 QUARRY ROAD
MANASSAS, VA
US 20110
Contact: MIKE MAYHUGH
MMAYHUGH@MCCLUNG-LOGAN.COM
T: (703)393-7344
F: (703)393-7844



OIL CONDITION

Visc @ 40°C	cSt	▲ 144	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ <1	---	---	---



WEAR METALS

Iron	ppm	■ 74	---	---	---
Copper	ppm	■ <1	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	■ 2	---	---	---
Magnesium	ppm	■ <1	---	---	---
Zinc	ppm	■ 0	---	---	---
Phosphorus	ppm	■ 1061	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 205	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot: VOLVO0002
Unique No: 10749051
Signed: Doug Bogart
Report Date: 19 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

