

CONSTRUCTION EQUIPMENT X36942 5547 - FRONT AXLE



Sample No: VCP414319
Oil Type: NOT GIVEN
Job No: X36942

VOLVO	INCODMATION			
	INFORMATION	<u>.</u>		
Sample Number		VCP414319	VCP387027	
Sample Date		10 Nov 2023	23 Nov 2022	
Machine Hours		5734	3143	
Oil Hours		0	0	
Oil Changed		N/A	Not Changd	
Sample Status		ABNORMAL	ABNORMAL	
OIL COND	DITION			
Visc @ 40°C	cSt	51.7	44.7	
CONTAM	ΙΝΔΤΙΩΝ			
		=12		
Silicon	ppm	13	12	
Sodium	ppm	3	0	
Potassium	ppm	0	0	
VOLVO				
WEAR M	ETALS			
Iron	ppm	64	■208	
Copper	ppm	41	1 38	
Lead	ppm	■ 0	0	
Tin	ppm	■<1	0	
Aluminum	ppm	2	1	
Chromium	ppm	2	5	
Molybdenum	ppm	0	3	
Nickel	ppm	■ <1	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	2	7	
Vanadium	ppm	0	0	
ADDITIV	FS			
		2200	m 2102	
Calcium	ppm	3299 18	3102	
Magnesium	ppm		□ 19 □ 1169	
Zinc	ppm	1362	□ 1168	
Phosphorus	ppm	1114	1047	
Barium	ppm	0	0	
Boron	ppm	102	1 71	



SCOTT EQUIPMENT COMPANY LLC - Baton Rouge 10160 AIRLINE HWY BATON ROUGE, LA US 70816 Contact: BRENT CALDWELL bcaldwell@scottcompanies.com T: (225)293-3683 F: (225)292-9658

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6242Unique No:10749070Signed:Doug BogartReport Date:19 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPHS

