

CONSTRUCTION EQUIPMENT

67338 A CUT ABOVE VOLVO 200E 314999 - HYDRAULIC SYSTEM

Sample No: VCP411976

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No: 67338 A CUT ABOVE

LUMUL	E INFORMATION				
				_	
Sample Number		VCP411976	 		
Sample Date		17 Nov 2023	 		
Machine Hours		469	 		
Oil Hours		0	 		
Oil Changed		N/A	 		
Sample Status		ATTENTION	 		
VOLVO					
OIL CON	IDITION				
Visc @ 40°C	cSt	42.5	 		
Acid Number (Al	N) ma KOH/a	■0.44	 		
	, , , , , , , , , , , , , , , , , , ,				
VOLVO	MINIATION				
LUNIA	MINATION				
Water	%	NEG	 		
Particles >4µm		△ 5063	 		
Particles >6µm		1927	 		
Particles >14µm		251	 		
ISO 4406:1999 (c)		20/18/15	 		
Silicon	ppm	■ 4	 		
Sodium	ppm	2	 		
Potassium	ppm	1	 		
WEAD	METALS				
_	ME I WE?				
ron	ppm	2	 		
Copper	ppm	12	 		
_ead	ppm	■0	 		
Γin	ppm	■0	 		
Aluminum	ppm	■ <1	 		
Chromium	ppm	■ <1	 		
Molybdenum	ppm	■0	 		
Nickel	ppm	■0	 		
Titanium	ppm	<1	 		
Silver	ppm	0	 		
Manganese	ppm	■<1	 		

COWIN EQUIPMENT COMPANY INC - GUNTERSVILLE 15101 ALABAMA HWY 20

MADISON, AL US 35756

Contact: RANDY HARRIS RHARRIS@COWIN.COM

T: (256)298-2322 F: (256)355-5250

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:COWMADUnique No:10749847Signed:Wes DavisReport Date:20 Nov 2023

53

■0 **■**510

■358

0

0

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES



CONSTRUCTION EQUIPMENT





GRAPHS

