

## CONSTRUCTION EQUIPMENT 413706 ALL COUNTY VOLVO EC 140E 314542 - REAR LEFT FINAL

Sample No: VCP440364

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 413706 ALL COUNTY

VOLVO				
SAMPLI	E INFORMATION	1		
Sample Number	•	VCP440364	VCP427181	 
Sample Date		13 Nov 2023	27 Jun 2023	 
Machine Hours		2892	2063	 
Oil Hours		0	0	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	ABNORMAL	 
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>275</b>	■136	 
VOLVO				
CONTAI	MINATION			
Silicon	ppm	<b>1</b> 5	<b>7</b> 1	 
Sodium	ppm	<b>■</b> 0	<b>6</b>	 
Potassium	ppm	<b>2</b>	<b>3</b>	 
WEAR I	METALS			
Iron	ppm	<b>410</b>	<u> </u>	 
Copper	ppm	■1	<b>4</b>	 
Lead	ppm	■0	<b>-</b> <1	 
Tin	ppm	<b>■</b> 9	<u>^</u> 56	 
Aluminum	ppm	<b>1</b>	□10	 
Chromium	ppm	<b>4</b>	<u>^</u> 20	 
Molybdenum	ppm	<b>2</b>	<b>-</b> <1	 
Nickel	ppm	<b>2</b>	6	 
Titanium	ppm	<1	1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>4</b>	<b>2</b> 0	 
Vanadium	ppm	0	<1	 
VOLVO				
ADDITIV	VES			
Calcium	ppm	<b>52</b>	□ 58	 
Magnesium	ppm	<b>11</b>	<b>2</b>	 
Zinc	ppm	44	■48	 
Phosphorus	ppm	<b>907</b>	■379	 
Barium	ppm	<b>■</b> <1	<b>1</b>	 
Boron	ppm	<b>120</b>	0	 



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10750323 Signed: Wes Davis Report Date: 19 Nov 2023



## **CONSTRUCTION EQUIPMENT**





