



# CONSTRUCTION EQUIPMENT

409192 RENTAL VOLVO A30G 75221 - TANK DIESEL EXHAUST FLUID (DEF)



**Sample No:** VCP440649  
**Oil Type:** {unknown}  
**Job No:** 409192 RENTAL



## SAMPLE INFORMATION

Sample Number	VCP440649	---	---	---
Sample Date	16 Nov 2023	---	---	---
Machine Hours	2481	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## CONTAMINATION

Hydrocarbon	scalar	■ NONE	---	---	---
-------------	--------	--------	-----	-----	-----

## DEF CONDITION

Urea Content	%	■ 32.7	---	---	---
Density @ 20°C	g/cm3	■ 1.0898	---	---	---
Refracting Index		■ 1.3828	---	---	---
Appearance	scalar	■ Clear & Bright	---	---	---

## Diagnosis

Fluid meets ISO 22241-2 requirements and is suitable for use. Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def). Urea content is normal.


**Depot:** VOLVO0093  
**Unique No:** 10750351  
**Signed:** Doug Bogart  
**Report Date:** 05 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS



Sample Color & Clarity

