

CONSTRUCTION EQUIPMENT VOLVO EC750EL 314205 - DIESEL ENGINE



Sample No: VCP434296

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

SAMPLE II	NFORMATION			
Sample Number	MI ONIMATION	VCP434296	VCP410854	
		14 Nov 2023	24 Jul 2023	
Sample Date				
Machine Hours		1470 0	691	
Oil Charact				
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIL CONDI	TION			
Visc @ 100°C	cSt	12.3	<u></u> 11.0	
Base Number (BN)		6.9	5.4	
Oxidation (PA)	%	93	76	
Oxidation (1 A)	70	33	70	
VOLVO				
CONTAMI	NATION			
Water	%	NEG	NEG	
Soot %	%	■1.1	□0.9	
Nitration (PA)	%	87	83	
Sulfation (PA)	%	67	63	
Glycol	%	■0.0	NEG	
Fuel	%	<1.0	□1.4	
Silicon	ppm	11	2 9	
Sodium	ppm	■0	4	
Potassium	ppm	■ 5	1 0	
	P.P			
VOLVO	TALC			
WEAR ME	IAL2			
Iron	ppm	■23	□34	
Copper	ppm	43	1 35	
Lead	ppm	■<1	2	
Tin	ppm	■ 2	6	
Aluminum	ppm	1	4	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	■ 53	66	
Nickel	ppm	■ 3	4	
Titanium	ppm	<1	<1	
Silver	ppm	■ 0	0	
Manganese	ppm	■<1	2	
Vanadium	ppm	0	<1	
ADDITIVE	S			
Calcium	ppm	1668	□ 2085	
Magnesium	ppm	471	258	
Zinc	ppm	1037	1128	
Phosphorus	ppm	■814	914	
Barium	ppm	■0	0	
	12 h	-42		



ALTA EQUIPMENT COMPANY 5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905

02 22202

Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO0090Unique No:10750519Signed:Jonathan HesterReport Date:22 Nov 2023

ppm

Boron



CONSTRUCTION EQUIPMENT





