



CONSTRUCTION EQUIPMENT

VOLVO L180H 5717 - REAR AXLE



Sample No: VCP376058
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No:



SAMPLE INFORMATION

Sample Number	VCP376058	---	---	---
Sample Date	13 Nov 2023	---	---	---
Machine Hours	1568	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302

OIL CONDITION

Visc @ 40°C	cSt	█ 40.8	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

WEAR METALS

Iron	ppm	█ 45	---	---	---
Copper	ppm	█ 10	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	█ 3638	---	---	---
Magnesium	ppm	█ 10	---	---	---
Zinc	ppm	█ 1538	---	---	---
Phosphorus	ppm	█ 1339	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 127	---	---	---

Depot: VOLVO0090
Unique No: 10750874
Signed: Angela Borella
Report Date: 21 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

