

Sample No: VCP401370

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: SWA412690 SW AG SVC

SAMPLE II	NFORMATION				
Sample Number	-	VCP401370			
Sample Date		13 Nov 2023			
Machine Hours		4225			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.38			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■NT			
Percentage Glycol	%	48.3			
Freezing Point	°C	□ -31			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Red			



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL

US 33905

Contact: TODD LARK tlark@altaequipfl.com

1:

F: (239)481-3302

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO0090Unique No:10750939Signed:Jonathan HesterReport Date:22 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPHS

