



# CONSTRUCTION EQUIPMENT

D12962 GLOBE CONSTR VOLVO L110H 632264 - REAR AXLE



**Sample No:** VCP429526  
**Oil Type:** VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102  
**Job No:** D12962 GLOBE CONSTR



ARING EQUIPMENT COMPANY INC - MAIN (MILWAUKEE)  
 13001 W SILVERE SPRING DR  
 BUTLER, WI  
 US 53007  
 Contact: GLENN OTTENBACHER  
 gottenbacher@aring.com  
 T: (262)282-0715  
 F: (262)781-5053



## SAMPLE INFORMATION

Sample Number	VCP429526	---	---	---
Sample Date	06 Nov 2023	---	---	---
Machine Hours	750	---	---	---
Oil Hours	750	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 40.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 3	---	---	---



## WEAR METALS

Iron	ppm	█ 104	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 7	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 3884	---	---	---
Magnesium	ppm	█ 8	---	---	---
Zinc	ppm	█ 1592	---	---	---
Phosphorus	ppm	█ 1303	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 144	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0069  
**Unique No:** 10751899  
**Signed:** Wes Davis  
**Report Date:** 21 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

