

Sample No: VCE63940
Oil Type: NOT GIVEN

Job No: 11556 SIOUX FALLS LF

CAMPLE	INFORMATION			
Sample Number		VCE63940	 	
Sample Number		11 Oct 2023		
Machine Hours		4790	 	
Oil Hours		0	 	
		N/A		
Oil Changed				
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	141	 	
		_		
VOLVO	WALE TANK			
LUNIAM	IINATION			
Water	%	▲ 1.02	 	
Silicon	ppm	53	 	
Sodium	ppm	27	 	
Potassium	ppm	11	 	
WEAR M	IETAI C			
_				
Iron	ppm	■108	 	
Copper	ppm	■ <1	 	
Lead	ppm	■0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■24	 	
Chromium	ppm	■2	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	1	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	<1	 	
ADDITIV	ES			
Calcium	ppm	20	 	
Magnesium	ppm	6	 	
Zinc	ppm	0	 	
Phosphorus	ppm	21	 	
Barium	ppm	0	 	
Boron	ppm	2	 	
DOTOIT	ppiii	_		



TRANSOURCE TRUCK & EQUIPMENT
901 EAST 60TH STREET NORTH
SIOUX FALLS, SD
US 57104
Contact: NATHAN MATZEN
nathan.matzen@transourceusa.com
T: (605)336-2000

Diagnosis

F: (605)336-2248

We advise that you check for the source of water entry. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0035Unique No:10751903Signed:Jonathan HesterReport Date:22 Nov 2023



CONSTRUCTION EQUIPMENT





