

## CONSTRUCTION EQUIPMENT SPM621864 VOLVO EC300EL 312535 - SWING DRIVE



Sample No: VCP433439

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SPM621864

VOLVO	INFORMATION			
	INFORMATION			
Sample Number		VCP433439	VCP358415	 
Sample Date		07 Nov 2023	22 Apr 2022	 
Machine Hours		3045	2032	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		ATTENTION	NORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>182</b>	<b>145</b>	 
		_		
VOLVO	UNIATION			
	IINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>15</b>	<b>4</b>	 
Sodium	ppm	■0	<b></b>	 
Potassium	ppm	<b>2</b>	<b>0</b>	 
VOLVO				
WEAR M	IETALS			
Iron	ppm	□106	<b>166</b>	 
Copper	ppm	<b>6</b>	<b>5</b>	 
Lead	ppm	■0	0	 
Tin	ppm	■0	0	 
Aluminum	ppm	<b>1</b>	<1	 
Chromium	ppm	<b>1</b>	2	 
Molybdenum	ppm	<b>4</b>	<b>-</b> <1	 
Nickel	ppm	<b>0</b>	0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>1</b>	<b>2</b>	 
Vanadium	ppm	0	0	 
	1.1.			
VOLVO	IEC			
ADDITIV	IT7			
Calcium	ppm	<u> </u>	<b>2</b> 1	 
Magnesium	ppm	■39	<b>-</b> <1	 
Zinc	ppm	<u> </u>	□10	 
Phosphorus	ppm	■848	■ 689	 
Barium	ppm	<b>■</b> 0	<b>0</b>	 
Boron	ppm	<b>23</b>	■86	 



BELSON STEEL
1685 N STATE RTE 50
BOURBONNAIS, IL
US 60914
Contact: M. POZAN
mpozan@belsonsteel.com
T: (815)932-7416
F:

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:BELBOUUnique No:10751924Signed:Jonathan HesterReport Date:22 Nov 2023

Contact/Location: M. POZAN - BELBOU



## **CONSTRUCTION EQUIPMENT**





