



# CONSTRUCTION EQUIPMENT

SPM633653 WM ROSCOE VOLVO L120H 633423 - FRONT AXLE



**Sample No:** VCP414264  
**Oil Type:** VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102  
**Job No:** SPM633653 WM ROSCOE



## SAMPLE INFORMATION

Sample Number	VCP414264	---	---	---
Sample Date	13 Nov 2023	---	---	---
Machine Hours	989	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA CONSTRUCTION EQUIPMENT**  
613 E STEVENSON RD  
OTTAWA, IL  
US 61350  
Contact: KEVIN SKRTICH  
KEVIN.SKRTICH@ALTAEQUIPMENT.COM  
T:  
F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 41.8	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 29	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 4	---	---	---



## WEAR METALS

Iron	ppm	█ 150	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	█ 11	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 10	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 3997	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1602	---	---	---
Phosphorus	ppm	█ 1308	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 158	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO5055  
**Unique No:** 10751940  
**Signed:** Wes Davis  
**Report Date:** 21 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

