



# CONSTRUCTION EQUIPMENT

SWA410367 TITAN AMER VOLVO L60H 622689 - TRANSMISSION (AUTO)



**Sample No:** VCP436034  
**Oil Type:** DEXRON III  
**Job No:** SWA410367 TITAN AMER



## SAMPLE INFORMATION

Sample Number	VCP436034	---	---	---
Sample Date	10 Nov 2023	---	---	---
Machine Hours	564	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

### ALTA EQUIPMENT COMPANY

5210 REESE ROAD  
DAVIE, FL  
US 33314

Contact: N. FACEY  
nfacey@altaequipfl.com  
T: (954)581-4744  
F: (954)583-0318



## OIL CONDITION

Visc @ 40°C	cSt	█ 28.3	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 80	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 7	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 78	---	---	---
Magnesium	ppm	█ 3	---	---	---
Zinc	ppm	█ 21	---	---	---
Phosphorus	ppm	█ 182	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 83	---	---	---

**Depot:** VOLVO0095  
**Unique No:** 10751991  
**Signed:** Sean Felton  
**Report Date:** 22 Nov 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

