



# CONSTRUCTION EQUIPMENT

SW1026389 BLUCON VOLVO L110H 632598 - TRANSMISSION (AUTO)



**Sample No:** VCP441010  
**Oil Type:** DEXRON III  
**Job No:** SW1026389 BLUCON



## SAMPLE INFORMATION

Sample Number	VCP441010	---	---	---
Sample Date	09 Nov 2023	---	---	---
Machine Hours	722	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ARNOLD MACHINERY COMPANY**  
4323 EAST WINSLOW AVENUE  
PHOENIX, AZ  
US 85040  
Contact: RANDY PRZEKURAT  
randyp@arnoldmachinery.com  
T:  
F: (602)414-1904



## OIL CONDITION

Visc @ 40°C	cSt	█ 28.9	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 36	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 75	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 2	---	---	---
Phosphorus	ppm	█ 178	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 96	---	---	---

**Depot:** VOLVO6174  
**Unique No:** 10751992  
**Signed:** Wes Davis  
**Report Date:** 21 Nov 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

