

CONSTRUCTION EQUIPMENT
SWA410173-30 NOT GIVEN VCP413177 (S/N NO INFO ON SIF/BOT

Sample No: VCP413177 Oil Type: **NOT GIVEN** Job No: SWA410173-30

SAMPLI	E INFORMATION	ı		
Sample Number		VCP413177	 	
Sample Date		16 Nov 2023	 	
Machine Hours		0	 	
Sample Status		ABNORMAL	 	
FIIFI (ONDITION			
Sulfur		-0		
	ppm	0	 	
Visc @ 40°C	cSt	2.43	 	
VOLVO				
CONTAI	MINATION			
Water	%	0.003	 	
Lead	ppm	■<1	 	
Nickel	ppm	■<1	 	
Aluminum	ppm	2	 	
Vanadium	ppm	0	 	
Silicon	ppm	-<1	 	



ALTA EQUIPMENT COMPANY

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

Diagnosis

This is a baseline read-out on the submitted sample. We recommend you service the filters on this component.All metal levels are normal indicating no corrosion in the system. Moderate concentration of visible dirt/debris present in the fuel. The water content is negligible. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO0095 **Unique No:** 10752038 Signed: Jonathan Hester Report Date: 22 Nov 2023



CONSTRUCTION EQUIPMENT





