

CONSTRUCTION EQUIPMENT BUREAU OF LAND MGMT VOLVO EC160E 31405 - COOLANT

Sample No: VCP403604

Oil Type: **VOLVO COOLANT VCS (YELLOW)**

Job No: **BUREAU OF LAND MGMT**

SAMPLE II	NFORMATION				
Sample Number	-	VCP403604			
Sample Date		14 Nov 2023			
Machine Hours		810			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.89			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■NT			
Percentage Glycol	%	49.3			
Freezing Point	°C	-33			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Yllow			



ARNOLD MACHINERY COMPANY 464 WASHINGTON STREET S TWIN FALLS, ID US 83301 Contact: JANAE HYMAS jhymas@arnoldmachinery.com T: (208)733-1715 F: (775)356-7152

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO1835 **Unique No:** 10752057 Signed: Jonathan Hester Report Date: 22 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPHS

