



# CONSTRUCTION EQUIPMENT

X58684 VOLVO A25G 752703 - REAR AXLE



**Sample No:** VCP425395

**Oil Type:** NOT GIVEN

**Job No:** X58684



## SAMPLE INFORMATION

Sample Number	VCP425395	---	---	---
Sample Date	16 Nov 2023	---	---	---
Machine Hours	1473	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
 PO BOX 997  
 SAINT ROSE, LA  
 US 70087  
 Contact: DANA FOSHEE  
 dfoshee@scottcompanies.com  
 T: (504)461-0961  
 F: (504)461-0970



## OIL CONDITION

Visc @ 40°C	cSt	87.2	---	---	---
-------------	-----	------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	4	---	---	---
Sodium	ppm	<1	---	---	---
Potassium	ppm	3	---	---	---



## WEAR METALS

Iron	ppm	181	---	---	---
Copper	ppm	19	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	4	---	---	---
Molybdenum	ppm	4	---	---	---
Nickel	ppm	2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	7	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	797	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	358	---	---	---
Phosphorus	ppm	1401	---	---	---
Barium	ppm	9	---	---	---
Boron	ppm	236	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** SCOSAI  
**Unique No:** 10753448  
**Signed:** Wes Davis  
**Report Date:** 22 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

