



# CONSTRUCTION EQUIPMENT

## X58883 VOLVO A25G 752694 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP413376  
**Oil Type:** VOLVO  
**Job No:** X58883



### SAMPLE INFORMATION

Sample Number	VCP413376	---	---	---
Sample Date	16 Nov 2023	---	---	---
Machine Hours	1461	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
 PO BOX 997  
 SAINT ROSE, LA  
 US 70087  
 Contact: DENISE CORVERS  
 dcorvers@scottcompanies.com  
 T: (504)461-0961  
 F: (504)461-0970



### OIL CONDITION

Visc @ 40°C	cSt	█ 89.5	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 3	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 203	---	---	---
Copper	ppm	█ 26	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	3	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	3	---	---	---
Manganese	ppm	6	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	850	---	---	---
Magnesium	ppm	<1	---	---	---
Zinc	ppm	364	---	---	---
Phosphorus	ppm	1344	---	---	---
Barium	ppm	3	---	---	---
Boron	ppm	222	---	---	---

**Depot:** SCOSAI  
**Unique No:** 10753453  
**Signed:** Wes Davis  
**Report Date:** 22 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

