

## **CONSTRUCTION EQUIPMENT**

SWA398817 COM METALS VOLVO EC350EL 314209 - REAR RIGHT

Sample No: VCP429223

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** SWA398817 COM METALS

VOLVO	LINEODMATIO	V		
	E INFORMATIO	N		
Sample Number		VCP429223	 	
Sample Date		27 Oct 2023	 	
Machine Hours		2103	 	
Oil Hours		1000	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
OIT CON	IDITION			
Visc @ 40°C	cSt	■346	 	
CONTAI	MINATION			
	<u></u>			
Water	%	NEG	 	
Silicon	ppm	<b>869</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>■</b> 20	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>2286</b>	 	
Copper	ppm	<b>■</b> 4	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<u>^</u> 20	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>■</b> 3	 	
Titanium	ppm	<b>19</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>19</b>	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	<b>■35</b>	 	
Magnesium	ppm		 	
Zinc	ppm	■0	 	
Phosphorus	ppm	 <b>■</b> 1126	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>148</b>	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0093Unique No:10753484Signed:Don BaldridgeReport Date:24 Nov 2023



## **CONSTRUCTION EQUIPMENT**





