



# CONSTRUCTION EQUIPMENT

X58890 VOLVO A25G 752834 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP426126  
**Oil Type:** NOT GIVEN  
**Job No:** X58890



## SAMPLE INFORMATION

Sample Number	VCP426126	---	---	---
Sample Date	17 Nov 2023	---	---	---
Machine Hours	439	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
PO BOX 997  
SAINT ROSE, LA  
US 70087  
Contact: DENISE CORVERS  
dcorvers@scottcompanies.com  
T: (504)461-0961  
F: (504)461-0970



## OIL CONDITION

Visc @ 40°C	cSt	■ 83.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 5	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 5	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 170	---	---	---
Copper	ppm	■ 16	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 3	---	---	---
Molybdenum	ppm	4	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	7	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	1150	---	---	---
Magnesium	ppm	5	---	---	---
Zinc	ppm	468	---	---	---
Phosphorus	ppm	1365	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	277	---	---	---

**Depot:** SCOSAI  
**Unique No:** 10754597  
**Signed:** Wes Davis  
**Report Date:** 26 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

