



CONSTRUCTION EQUIPMENT

X58891 VOLVO A25G 752900 - FRONT AXLE



Sample No: VCP426318
Oil Type: NOT GIVEN
Job No: X58891



SAMPLE INFORMATION

Sample Number	VCP426318	---	---	---
Sample Date	17 Nov 2023	---	---	---
Machine Hours	522	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

SCOTT EQUIPMENT COMPANY LLC - Saint Rose
 PO BOX 997
 SAINT ROSE, LA
 US 70087
 Contact: DENISE CORVERS
 dcorvers@scottcompanies.com
 T: (504)461-0961
 F: (504)461-0970



OIL CONDITION

Visc @ 40°C	cSt	█ 90.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 5	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 263	---	---	---
Copper	ppm	█ 30	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 5	---	---	---
Molybdenum	ppm	5	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	10	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	716	---	---	---
Magnesium	ppm	3	---	---	---
Zinc	ppm	316	---	---	---
Phosphorus	ppm	1387	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	266	---	---	---

Depot: SCOSAI
Unique No: 10754605
Signed: Wes Davis
Report Date: 26 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

