



CONSTRUCTION EQUIPMENT

DIAMOND BACK SERVICE YANMAR UI055-6A JAH464 - COOLANT



Sample No: VCP412510
Oil Type: NOT GIVEN
Job No: DIAMOND BACK SERVICE



SAMPLE INFORMATION

Sample Number	VCP412510	---	---	---
Sample Date	15 Nov 2023	---	---	---
Machine Hours	1967	---	---	---
Sample Status	NORMAL	---	---	---

ROMCO INC
1350 NE LOOP 820
FORT WORTH, TX
US 76106
Contact: CHRIS BITNER
CBitner@romco.com
T:
F: (817)626-8983



COOLANT CONDITION

pH	Scale 0-14	■ 8.57	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 600	---	---	---
Percentage Glycol	%	■ 54.1	---	---	---
Freezing Point	°C	■ -45	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Green	---	---	---

Depot: VOLVO0081
Unique No: 10754720
Signed: Jonathan Hester
Report Date: 27 Nov 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

