



# CONSTRUCTION EQUIPMENT

386207 VOLVO L60H 621053 - DIESEL ENGINE



**Sample No:** VCP408486  
**Oil Type:** VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3  
**Job No:** 386207



**ALTA EQUIPMENT COMPANY- BYRON CENTER**  
 8840 BYRON COMMERCE DR SW  
 BYRON CENTER, MI  
 US 49315  
 Contact: BRIAN RESER  
 brian.reser@altaequipment.com  
 T: (616)878-7450  
 F: (616)878-7650



## SAMPLE INFORMATION

Sample Number	VCP408486	---	---	---
Sample Date	23 Oct 2023	---	---	---
Machine Hours	2034	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 100°C	cSt	█ 13.2	---	---	---
Base Number (BN)	mg KOH/g	█ 10.6	---	---	---
Oxidation (PA)	%	77	---	---	---



## CONTAMINATION

Water	%	NEG	---	---	---
Soot %	%	█ 0.2	---	---	---
Nitration (PA)	%	62	---	---	---
Sulfation (PA)	%	59	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---



## WEAR METALS

Iron	ppm	█ 8	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 6	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 52	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█ 1706	---	---	---
Magnesium	ppm	█ 615	---	---	---
Zinc	ppm	█ 1231	---	---	---
Phosphorus	ppm	█ 934	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 62	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

**Depot:** VOLVO0046  
**Unique No:** 10755201  
**Signed:** Wes Davis  
**Report Date:** 27 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

