

## CONSTRUCTION EQUIPMENT VOLVO EC160EL 310424 - SWING DRIVE



Sample No: VCP412647

**Oil Type:** DRYDENE LIMITED SLIP GEAR 80W90

Report Id: DHFCOL [WUSCAR] 06016809 (Generated: 11/28/2023 15:59:56) Rev: 1

Job No:

VOLVO					
CAMDIC	E INFORMATION				
	INFURMATION		_		
Sample Number		VCP412647	VCP361155		
Sample Date		20 Nov 2023	14 Jun 2022		
Machine Hours		4000	3000		
Oil Hours		1000	1000		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
OIL CON	DITION				
Visc @ 40°C	cSt	<b>126</b>	<b>124.3</b>		
VOLVO					
CONTAMINATION					
Water	%	NEG	NEG		
Silicon	ppm	■8	<b>8</b>		
Sodium	ppm	<b>■&lt;1</b>	□0		
Potassium	ppm	<b>■&lt;1</b>	<b>-</b> <1		
VOLVO	AFTALC.				
WEAR N	AF LALZ				
Iron	ppm	<b>67</b>	■99		
Copper	ppm	<b>2</b>	<b>3</b>		
Lead	ppm	■0	<b>0</b>		
Tin	ppm	■0	0		
Aluminum	ppm	<b>■&lt;1</b>	3		
Chromium	ppm	■0	1		
Molybdenum	ppm	<b>4</b>	<b>2</b>		
Nickel	ppm	■0	0		
Titanium	ppm	0	<1		
Silver	ppm	0	0		
Manganese	ppm	<1	<b>1</b>		
Vanadium	ppm	0	0		
ADDITIV	VES				
Calcium	ppm	<b>73</b>	<b>1</b> 06		
Magnesium	ppm	<b>■20</b>	■35		
Zinc	ppm	<b>55</b>	<b>6</b> 5		
Phosphorus	ppm	■859	879		
Barium	ppm	<b>0</b>	<b>0</b>		
Boron	ppm	<b>135</b>	<b>164</b>		



DH FUNK AND SONS LLC 3995 CONTINENTAL DRIVE COLUMBIA, PA US 17512 Contact: GARY SHEPHERD GSHEPHERD@DHFUNK.COM T:

F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: DHFCOL
Unique No: 10755953
Signed: Sean Felton
Report Date: 28 Nov 2023



## **CONSTRUCTION EQUIPMENT**





