CONSTRUCTION EQUIPMENT X58888 VOLVO ECR235EL 315288 - REAR LEFT FINAL DRIVE

 Sample No:
 VCP426139

 Oil Type:
 NOT GIVEN

 Job No:
 X58888

VOLVO

SAMPLE INFORMATION

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

	. INFUKMATIUN			
Sample Number	-	VCP426139	VCP385995	
Sample Date		20 Nov 2023	19 May 2023	
Machine Hours		1955	1237	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	321	1 78	
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	15	23	
Sodium	ppm	1	2	
Potassium	ppm		2	
	T.F.			
WEAR N	AFTAIS			
			- 425	
lron	ppm	65	135	
Copper	ppm	0	□ <1	
Lead 	ppm	0	0	
Tin	ppm	0	<1	
Aluminum	ppm	□ <1	1	
Chromium	ppm	2	4	
Molybdenum	ppm	0	<1	
Nickel	ppm	0	<1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	<1	3	
Vanadium	ppm	0	0	
VOLVO				
ADDITIN	ES			
a. I. :				-

5

10

265

0

0



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997

 SAINT ROSE, LA US 70087
 Contact: DENISE CORVERS dcorvers@scottcompanies.com
 T: (504)461-0961
 F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10755970Signed:Sean FeltonReport Date:28 Nov 2023

50

0

27

925


139

0

CONSTRUCTION EQUIPMENT



VOLVO



Report Id: SCOSAI [WUSCAR] 06016826 (Generated: 11/29/2023 19:23:55) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI