CONSTRUCTION EQUIPMENT X58888 VOLVO ECR235EL 315288 - SWING DRIVE



Sample No:	VCP426145
Oil Type:	NOT GIVEN
Job No:	X58888

VOLVO

SAMPLE INFORMATION VCP426145 Sample Number Sample Date 20 Nov 2023 Machine Hours 1955 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 180 CONTAMINATION Water % NEG Silicon 13 ppm Sodium 2 ppm Potassium ppm 0 WEAR METALS Iron ppm 138 Copper ppm 20 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm ■<1 Chromium 2 ppm Molybdenum ppm <1 Nickel 0 ppm Titanium 0 ppm Silver 0 ppm Manganese ppm 3 Vanadium ppm 0 101 **ADDITIVES** Calcium 5 ppm Magnesium 0 ppm



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com

T: (504)461-0961 F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 SCOSAI

 Unique No:
 10755972

 Signed:
 Sean Felton

 Report Date:
 28 Nov 2023

23

387

2

10

ppm

ppm

ppm

ppm

Zinc

Barium

Boron


Phosphorus

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SCOSAI [WUSCAR] 06016828 (Generated: 11/29/2023 19:24:12) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI