

CONSTRUCTION EQUIPMENT

SWA401510 RENTAL EQU TADANO GR350XL 562450 - DIESEL EN



Potassium

ppm

2

Oil Type: DIESEL ENGINE OIL SAE 5W40

Job No: SWA401510 RENTAL EQU

SAMPLE II	NFORMATION			
Sample Number		VCP440538	 	
Sample Date		17 Nov 2023	 	
Machine Hours		1147	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	13.2	 	
Base Number (BN)	mg KOH/g	5.7	 	
Oxidation (PA)	%	82	 	
CONTAMI	MULTUN			
	-		_	
Water	%	NEG	 	
Soot %	%	■ 0.2	 	
Nitration (PA)	%	85	 	
Sulfation (PA)	%	63	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	44	 	
Sodium	ppm	5	 	

WEAR N	METALS			
Iron	ppm	■39	 	
Copper	ppm	188	 	
Lead	ppm	<u> </u>	 	
Tin	ppm	-<1	 	
Aluminum	ppm	■8	 	
Chromium	ppm	1	 	
Molybdenum	ppm	59	 	
Nickel	ppm	■0	 	
Titanium	ppm	1	 	
Silver	ppm	■0	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	

ADDIT	Zavi			
Calcium	ppm	1783	 	
Magnesium	ppm	■381	 	
Zinc	ppm	1202	 	
Phosphorus	ppm	■860	 	
Barium	ppm	■8	 	
Boron	ppm	■55	 	



ALTA EQUIPMENT CO - ORLAND PARK
5000 INDUSTRIAL HWY
GARY, IN
US 46406
Contact: DAVE ENG
DAVE.ENG@ALTG.COM
T: (312)350-2560
F:

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Elemental level of silicon (Si) above normal indicating ingress of seal material. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8885Unique No:10762485Signed:Don BaldridgeReport Date:29 Nov 2023



CONSTRUCTION EQUIPMENT





